# **Electricity Safety - Bushfire Mitigation Plan**

Classification: ☐ Confidential ☐ Restricted ☑ Unclassified ☐ Internal

Authoriser: Responsible: Folder: Name Provided Electrical Safety Management System VESMS - Voluntary Electricity Safety 

 Page:
 1 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

#### **REVISIONS**

REV No.	AUTHOR	DATE	DESCRIPTION OF CHANGE			
1	Name provided	28 Jun 2023	Initial version issued to ESV			
2	Name provided	30 Jun 2023	Revised following internal comments			
3	Name provided	27 Sep 2023	Updated to incorporate ESV comments			

Authoriser: Name Provided Page: 2 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

#### **Contents**

Pι	ırpose	5
Sc	cope:	5
Re	esponsibilities & Authorities	5
3.1	HBESS Co-ordinator:	5
3.2	2 Facility Manager	6
Pr	escribed Particulars	6
4.1 Ele	The name address, email address and telephone number of the specified operator- reg 6, para (a certricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):	a) 6
4.2 Lic	The name address, email address and telephone number of the Electricity Generation and Sale tence holder - section 18 of the Electricity Industry Act 2000 (Vic):	6
4.3 Mi	Person responsible for the preparation of the Plan- reg 6, para (b) Electricity Safety (Bushfire tigation) Regulations 2023 (Vic):	6
4.4 Re	Person responsible for carrying out the Plan- reg 6, para (c) Electricity Safety (Bushfire Mitigation egulations 2023 (Vic):	1) 7
4.5 Re	Specified Operator's control room- reg 6, para (d) Electricity Safety (Bushfire Mitigation) egulations 2023 (Vic):	7
4.6	6 Facility Manager:	7
4.7	Emergency Commander (24/7):	7
4.8	Stakeholder Engagement contact:	7
4.9	Fire Policies - reg 6, para (e) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):	7
4.1	0 Relationship between HBESS and HRP FRMP:	8
4.1 at-	Objectives of the plan to achieve the mitigation of fire danger arising from the specified operator's risk electric lines - reg 6, para (f) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):	s 8
loc	2 A description, map, or plan of the land to which the bushfire mitigation plan applies, identifying th action of the specified operator's at-risk electric lines reg 6, para (g) Electricity Safety (Bushfire tigation) Regulations 2023 (Vic):	e 8
4.1	13 ESV exemptions:	8
	Preventative strategies - reg 6, para (h) Electricity Safety (Bushfire Mitigation) Regulations 2023 (c): 8	
4.1 Re	Plan for inspection of electrical assets - reg 6, para (i) Electricity Safety (Bushfire Mitigation)	8
the	Details of the processes and procedures for ensuring that each person who is assigned to carry or inspections referred to in paragraph (i)- reg 6, para (j) Electricity Safety (Bushfire Mitigation) egulations 2023 (Vic):	out 9
in	Problem 17 Details of the processes and procedures for ensuring that persons (other than persons referred to paragraph (j)) who carry out or will carry out functions under the plan are competent to do so - reg 6, ra (k) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):	0
	8 Operation and Maintenance Plans for at-risk electrical lines - reg 6, para (I) Electricity Safety ushfire Mitigation) Regulations 2023 (Vic):	10
	4.18.1 In the event of a fire:	10
	4.18.2 During a day of Total Fire Ban:	10
	4.18.3 During a fire danger period:	10
4.1 fro	Investigations, analysis and methodology to be adopted for the mitigation of the risk of fire ignitio m at-risk electrical lines- reg 6, para (m) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vio 11	
4.2 Mi	20 Specified Operator's Processes and Procedures - reg 6, para (n) Electricity Safety (Bushfire tigation) Regulations 2023 (Vic):	11
	4.20.1 Monitor the implementation of the Plan:	11

Authoriser: Name Provided Page: 3 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 28/06/2024 **Review Date:** 

	4.20.2 Audit the implementation of the Plan:	11
	4.20.3 Identify any deficiencies in the Plan or the Plan's effectiveness:	12
	4.20.4 Change the Plan and the Plan's implementation to rectify any deficiencies identified:	12
	4.20.5 Monitor the effectiveness of inspections carried out under the Plan:	12
	4.20.6 Audit the effectiveness of inspections carried out under the Plan:	12
	4.21 The policy in relation to assistance to be provided to fire control authorities in the investigation fires near the specified operator's at-risk electrical lines - reg 6, para (o) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):	of 12
5	Accessibility of Documents	13
6	References	14
App	endix A - Hazelwood BESS Locality Map	15
App	endix B - HBESS High risk transmission line assets	16
App	endix C - Maintenance summary	17
Ann	endix D - Flectricity Generation And Sale Licence	20

Authoriser: Name Provided Page: 4 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

#### 1 Purpose

The Hazelwood BESS Project Co Pty Ltd operates the Hazelwood Battery Energy Storage System (HBESS) under an Electricity Generation and Sale Licence issued to Hazelwood BESS Project Co Pty Ltd by the Essential Services Commission (ESC) of Victoria on 10 August 2022. A copy of the licence is included at Appendix D.

HBESS is fully enclosed by the Hazelwood Rehabilitation Project's (HRP) land and is within the boundary of Mining License MIN5004. The HRP land has been classified by the CFA as a hazardous bushfire area.

Hazelwood BESS Project Co Pty Ltd as a business that has electrical transmission lines above its premises at HBESS, which includes a hazardous bushfire area, meets the definition of a "Specified Operator". As such, Hazelwood BESS Project Co Pty Ltd for the HBESS must have systems in place to manage its obligations as a Specified Operator.

This Electricity Safety – Bushfire Mitigation Plan (the Plan), amongst other systems of work, helps HBESS meet its specified obligations and ensures ongoing risk management and compliance with the requirements of relevant Victorian legislation related to the operations and maintenance of overhead electrical assets.

Namely, the relevant Regulations are the:

- Electricity Safety Act 1998 (Vic)
- Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic)
- Electricity Safety (Electric Line Clearance) Regulations 2020 (Vic)

#### 2 Scope:

This plan details the practices and procedures in place at HBESS for the prevention of fire caused by overhead electrical assets and the mitigation of any fire incident that may occur.

In recognition of the HBESS site location, and the fact that the "at risk" electrical line sits on land subject to Mining Licence 5004, HBESS leverages policies and procedures of Hazelwood Power (including the Hazelwood Power Electricity Safety – Bushfire Mitigation Plan and Hazelwood Power Health & Safety Mine Fire Service Policy [Paradigm OrigID 2589]) to assist in the development of the Plan.

#### 3 Responsibilities & Authorities

#### 3.1 HBESS Co-ordinator:

The HBESS Co-ordinator shall ensure that all operational personnel and contractors including the Facility Manager understand their responsibilities and comply with the Plan.

The HBESS Co-ordinator shall ensure that:

- the processes and procedures required to comply with the applicable Regulations are in place and followed;
- the Plan is reviewed and updated annually to comply with the Regulations and ensure that any changes to relevant operational procedures are compliant with the Regulations and reflected in the Plan;
- any vegetation pruning or removal is conducted in consultation with the HRP environmental management team;

Authoriser: Name Provided Page: 5 of 21 Ver/Status: 03 / Current Responsible: OrigID: 58284 **Version Date:** Electrical Safety Management System 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

- an audit process is in place to ensure that the requirements of the Plan and associated regulatory requirements are being met;
- a copy of the current Plan is submitted to Energy Safe Victoria (ESV) annually before 1 July each year;
- · each revised Plan gains ESV Acceptance; and
- the accepted Plan is made available on the HBESS website and head office.

#### 3.2 Facility Manager

The contractor Facility Manager shall ensure that all contractor operational personnel and subcontractors understand their responsibilities and comply with the Plan.

#### 4 Prescribed Particulars

4.1 The name address, email address and telephone number of the specified operator- reg 6, para (a) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Name: HAZELWOOD BESS PROJECT CO PTY LTD ACN 643 891 703 as trustee for

the HBESS ASSET TRUST ABN 34 755 328 434

Email: enquiries.au@engie.com

Address: Level 23, 2 Southbank Boulevard, Southbank VIC 3006

Phone No: (03) 9617 8400

Business Hours: 9am – 5pm Monday - Friday

4.2 The name address, email address and telephone number of the Electricity Generation and Sale Licence holder - section 18 of the Electricity Industry Act 2000 (Vic):

Name: HAZELWOOD BESS PROJECT CO PTY LTD ACN 643 891 703 as trustee for

the HBESS ASSET TRUST ABN 34 755 328 434

Email: enquiries.au@engie.com

Address: Level 23, 2 Southbank Boulevard, Southbank VIC 3006

Phone No: (03) 9617 8400

4.3 Person responsible for the preparation of the Plan- reg 6, para (b) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Name: HBESS Project Onsite Representative

Email: enquiries.au@engie.com

Address: 1 Hazelwood Drive, Hazelwood, PO Box 195, Morwell VIC 3840

Phone No: (03) 9617 8400

Authoriser: Name Provided Page: 6 of 21 Ver/Status: 03 / Current Electrical Safety Management System OrigID: **Version Date:** Responsible: 58284 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

### 4.4 Person responsible for carrying out the Plan- reg 6, para (c) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Name: HBESS Co-ordinator

Email: enquiries.au@engie.com

Address: 1 Hazelwood Drive, Hazelwood, PO Box 195, Morwell VIC 3840

Phone No: 03) 9617 8400

### 4.5 Specified Operator's control room- reg 6, para (d) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Email: enquiries.au@engie.com

Phone No: (03) 9617 8400

#### 4.6 Facility Manager:

Name: Facility Manager

Email: enquiries.au@engie.com

Address: 525 Collins St, Suite 212 Spaces Rialto Melbourne VIC 3000 Australia

Phone No: (03) 9617 8400

#### 4.7 Emergency Commander (24/7):

Name: Emergency Commander (Security and Emergency Service Contractor)

Address: 1 Hazelwood Drive, Hazelwood, PO Box 195, Morwell VIC 3840

Phone No: (03) 5135 3333

#### 4.8 Stakeholder Engagement contact:

Name: HBESS Stakeholder Engagement Manager

Address: Level 23, 2 Southbank Boulevard, Southbank VIC 3006

Phone No: (03) 9617 8400

### 4.9 Fire Policies - reg 6, para (e) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

HBESS manages and maintains its overhead line infrastructure to ensure that the probability of overhead electrical lines causing a fire is minimised, in the known high-risk environment of the HRP.

The HBESS Fire Management policy is currently being finalised by the Specified Operator and will be implemented as soon as possible.

The existing Hazelwood Power Health & Safety Mine Fire Service Policy [Paradigm OrigID 2589], provides a framework of standards and guidelines which are aimed at:

- Outlining management's commitment to minimising the risks associated with fire at the HRP which encloses the HBESS site;
- Protecting the safety of employees, contractors and third parties attending the site;

Authoriser: Name Provided Page: 7 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 **Version Date:** 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

- Protecting HRP assets, infrastructure and exposed coal reserves;
- Minimising fire-related disruptions to the decommissioning, demolition and rehabilitation operations;
- Providing a means of promptly reporting, containing and extinguishing fires at the HRP site;
- Preventing the development of a major coal fire giving rise to impacts on third parties and the environment; and
- Ensuring that all HRP infrastructure for fire prevention, mitigation, and suppression meets industry best practice, and operational requirements.

These requirements are delivered through the HRP Fire Risk Management Plan [Paradigm OrigID 56965] (FRMP).

#### 4.10 Relationship between HBESS and HRP FRMP:

HRP is required to ensure that its FRMP maintains processes and procedures that control the risks of its operations so as to not cause a fire, in a known high-risk environment. Given the location of HBESS, HBESS is included in the risk assessment of the HRP FRMP.

4.11 Objectives of the plan to achieve the mitigation of fire danger arising from the specified operator's at-risk electric lines - reg 6, para (f) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

To ensure that effective risk minimisation is achieved, the HBESS "at-risk" electric line is regularly inspected and vegetation is removed where identified.

4.12 A description, map, or plan of the land to which the bushfire mitigation plan applies, identifying the location of the specified operator's at-risk electric lines. - reg 6, para (g) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

A plan showing HBESS located to the south of the Latrobe City township of Morwell and a site locality map is shown at Appendix A. The HBESS site and at risk electric lines are wholly within an area assigned by the Country Fire Authority (CFA) as a "High" Fire Hazard Rating.

A drawing of the HBESS site and the "at-risk" electrical line assets is shown at Appendix B.

The "at risk" electrical line is the entirety of the HWPS-HWBS transmission line connecting the HBESS to the AusNet Hazelwood Switchyard.

#### 4.13 ESV exemptions:

HBESS does not have any existing authorised ESV exemptions to Regulations and/or Sub Regulations with reference to the relevant electrical infrastructure (at risk electric lines) located on the HRP site.

4.14 Preventative strategies - reg 6, para (h) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

HBESS undertakes line clearance assessments and vegetation removal and/or pruning in accordance with the HBESS Electric Line Clearance Plan [HBESS-OP-D-0002].

Prior to construction of the at risk line approximately 12 months ago all infringing vegetation was removed and no outstanding clearing requirements remain.

Authoriser: Name Provided

Responsible: Electrical Safety Management System

VESMS - Voluntary Electricity Safety

 Page:
 8 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

All electrical overhead lines are routinely visually inspected in accordance with the HBESS HV Maintenance Plan [14343-OAM-FLN-90-001] – see the maintenance summary in Appendix C Maintenance summary for further details. Vegetation line clearance inspections are ground based visual inspections, with the full length of the line and area beneath, visible from the ground at pole 2.

All faults are recorded, and managed, through the HBESS CMMS. Line clearance defects are to be immediately actioned and specialist qualified resources engaged to undertake pruning or clearing. All pruning and clearing is conducted in consultation with the HRP environmental management team and in accordance with the HBESS Electric Line Clearance Plan [HBESS-OP-D-0002].

Other line defects identified during the inspection process are prioritised based upon the fault. Three priorities for rectification are assessed, high – immediate to 30 days, medium – 30 days to 6 months, low – 6 months to 3 years.

The recording of defects in the HBESS CMMS allows HBESS personnel to independently review all reported faults as an audit of the inspection work and timely rectification of defects.

### 4.15 Plan for inspection of electrical assets - reg 6, para (i) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

The HBESS specified operator has an O&M Agreement in place with the Facility Manager to provide an inspection of all overhead high voltage power lines ("at risk" electric lines) on a three-yearly cycle, with a general inspection and vegetation assessment every six months.

Appendix C - Maintenance summary details the inspections and assessments undertaken during each cycle.

## 4.16 Details of the processes and procedures for ensuring that each person who is assigned to carry out the inspections referred to in paragraph (i)- reg 6, para (j) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

All persons shall only perform work for which they are qualified, competent and trained.

The Facility Manager ensures anyone employed or engaged in respect of any activities connected with the HBESS operations and maintenance including line inspections possesses the appropriate skill, expertise, approvals and qualifications. The assessment is undertaken in accordance with the HBESS Project Health and Safety Management Plan [14343-HAS-GEN-90-001].

The Facility Manager engages the resources, arranges their access to the site, checks competencies prior to commencement, and monitors progress.

All persons carrying out line inspections are employees or contractors of the Facility Manager and complete full inductions to site prior to entry. The induction process details the minimum requirements for carrying out work on site including the requirement to report all incidents to the Specified Operator.

Three yearly inspections are completed by persons with a Certificate II Accreditation in Asset Inspection (or equivalent as approved by ESV).

Inspector qualifications are checked by the Specified Operator, as part of the ENGIE Group Health & Safety Rule Health & Safety with regard to Contractors and Subcontractors [GHSD-GOV-GR-02], when notified by the Facility Manager of the inspection.

### 4.17 Details of the processes and procedures for ensuring that persons (other than persons referred to in paragraph (j)) who carry out or will carry out functions

Authoriser: Name Provided

Responsible: Electrical Safety Management System

Folder: VESMS - Voluntary Electricity Safety

 Page:
 9 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

### under the plan are competent to do so - reg 6, para (k) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Other personnel carrying out inspections, as part of normal operational activities on the transmission system, are trained by Registered Training Organisations to Units of Competency in the Australian Qualifications Framework as Electrical Operators and authorised by the Specified Operator to operate the HBESS high voltage transmission line.

The Facility Manager ensures anyone employed or engaged in respect of any activities connected with the HBESS operations and maintenance including line inspections possesses the appropriate skill, expertise, approvals and qualifications. The assessment is undertaken in accordance with the HBESS Project Health and Safety Management Plan [14343-HAS-GEN-90-001].

All persons on site who are carrying out functions under the plan complete full inductions to site prior to entry. The induction process details the minimum requirements for carrying out work on site including the requirement to report all incidents to the Specified Operator.

The HBESS Co-ordinator undertakes auditing to verify site inductions, competencies, and site activities are compliant with the Plan.

### 4.18 Operation and Maintenance Plans for at-risk electrical lines - reg 6, para (I) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

These plans include safeguards that enable the HBESS transmission line to continue to operate 24/7.

#### 4.18.1 In the event of a fire:

In the event of a fire:

- The HBESS transmission line ("at risk electrical equipment") is designed to operate without substantial impairment, so as to ensure power supply is maintained.
- Any non-essential planned critical asset maintenance activity will be cancelled in order to ensure that all available HBESS personnel can be called upon to assist with the fire response.
- In the event of a major fire within the business, the Project Emergency Response Plan [14343-HAS-GEN-90-003] shall be implemented and actions necessary to protect the HBESS's power systems will be directed by the HRP Emergency Commander or the CFA/FRV Incident Controller with technical support from HBESS personnel.

#### 4.18.2 During a day of Total Fire Ban:

During a day of Total Fire Ban all transmission line non-essential planned maintenance activity shall be cancelled and any essential maintenance which is proposed to proceed, will be risk assessed to ensure that it does not constitute a fire risk.

#### 4.18.3 During a fire danger period:

During a fire danger period all inspections and high priority maintenance work shall have been completed prior to the start of the fire danger period to minimise fire risk due to the transmission equipment. Any required vegetation removal will have been completed.

Due to the inherent Hazelwood Power Mine fire risk and the HBESS residing within the Mine licence, HBESS shall respect a declaration of a Fire Season for the Mine by Hazelwood Power, which is independent of the CFA declared season (which typically takes effect some time prior to the CFA fire season). The declaration of a Mine Fire Season under the Hazelwood Power Fire Readiness Planning Guidelines [Paradigm OrigID 36546] initiates a series of preparatory measures within the

03 / Current

27/09/2023

28/06/2024

Authoriser: Name Provided Page: 10 of 21 Ver/Status:

Responsible: Electrical Safety Management System OrigID: 58284 Version Date:

Folder: VESMS - Voluntary Electricity Safety DocID: 58284 Review Date:

Mine to ensure all protective equipment and systems are serviceable and that necessary training and inspections have been conducted to implement a high level of preparedness.

# 4.19 Investigations, analysis and methodology to be adopted for the mitigation of the risk of fire ignition from at-risk electrical lines- reg 6, para (m) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

HBESS site and Mine fire incidents are reported and investigated in accordance with the HBESS Project Health and Safety Management Plan [14343-HAS-GEN-90-001], and HBESS Incident Notification Guideline [14343-HAS-GEN-90-009] using the HBESS incident management portal (Salesforce).

Mine fire is subject to risk assessment under the current Victorian Occupational Health and Safety Regulations. Under these regulations fire has been determined to be a Major Mining Hazard. In accordance with the requirements of these Regulations, a detailed risk assessment has been undertaken and a series of control measures established to reduce risks to the extent that is reasonably practicable. These risk assessments and control measures are subject to periodic review in accordance with the requirements of the Regulations, and oversight from the relevant Regulator (WorkSafe Victoria).

In addition to meeting its WorkSafe commitments HRP is required to assess risks that may have the potential to impact upon public health and safety, community facility and the environment. HRP assess those risks through its Risk Management Plan (RMP) (formally the Risk Assessment and Management Plan (RAMP)), a requirement of the Mining License under the *Mineral Resources* (Sustainable Development) (Mineral Industries) Regulations 2013, Schedule 15. The RMP provides a detailed assessment of mine fire and the prevention and mitigation measures implemented and incorporated into its policies and procedures. It is also a condition of the license that the RMP must be approved by the Department Head of the Department of Jobs, Precincts and Regions Earth Resources Regulation (DJPR ERR). HBESS is included in the HRP risk assessment.

All Mine fires are reported to WorkSafe, CFA, Fire Rescue Victoria (FRV) and DJPR ERR on an incident-by-incident basis. Additionally, a summary of all fires on site are sent to FRV, CFA and DJPR ERR, for further review and oversight, on a monthly basis.

No fire activity has been experienced in the HBESS at-risk transmission line area during or since the construction of the HBESS at-risk line.

### 4.20 Specified Operator's Processes and Procedures - reg 6, para (n) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

Below are details of the processes and procedures by which the specified operator will take certain action.

#### **4.20.1 Monitor the implementation of the Plan:**

Biannually, the HBESS Co-ordinator monitors the completion of the transmission line assessments provided in Appendix C - Maintenance summary

#### 4.20.2 Audit the implementation of the Plan:

In addition to the audits conducted by the HBESS Co-ordinator in section 4.17 above, all elements of regulatory compliance are audited/inspected by ENGIE internal personnel/auditors. In addition to internal audits, the HRP site (which includes HBESS) is audited/inspected by Independent Auditors and various Regulators, including DJPR ERR and WorkSafe. The Regulators have adopted a process of audits and HRP site inspections specifically related to fire, both prior to and during the declared fire season.

Authoriser: Name Provided

Responsible: Electrical Safety Management System

VESMS - Voluntary Electricity Safety

Folder:

 Page:
 11 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

#### 4.20.3 Identify any deficiencies in the Plan or the Plan's effectiveness:

The HRP fire policies and procedures (including HBESS assets) are reviewed annually prior to the commencement of the Annual Fire Season declared for the HRP Mine as per the Mine Pre-Fire Season Checklist [Paradigm OrigID 36549].

In addition, business processes ensure the update of policies and procedures based on input from any incident investigations, internal audits, external audits, Regulator reviews, etc., by logging and monitoring of action items using the HBESS incident management portal (Salesforce).

The Regulator audits relating to fire preparedness are conducted by WorkSafe and DJPR ERR and can also identify deficiencies in the plans or systems in use on site. Recommendations from the Regulators are enforceable and must be complied with.

#### 4.20.4 Change the Plan and the Plan's implementation to rectify any deficiencies identified:

As noted in 4.20.3 above, ENGIE has a process to capture and implement improvements for policies and procedures based on findings, recommendations and / or employee suggestions.

#### 4.20.5 Monitor the effectiveness of inspections carried out under the Plan:

All contractors working on site are subject to routine inspections and audit under the ENGIE Group Health & Safety Rule Health & Safety with regard to Contractors and Subcontractors [GHSD-GOV-GR-02].

In accordance with the group rules, the Operations Manager and/or the HBESS Co-ordinator check and monitor the contractor once on site and confirm that all health and safety requirements are being met, the contractor's personnel are qualified and licensed for the work they are performing, and documented work procedures are being followed to the required standard.

#### 4.20.6 Audit the effectiveness of inspections carried out under the Plan:

Compliance audits, inspections and reviews are undertaken on the HBESS site by HBESS internal nominated auditors/inspectors, independent auditors and various Regulatory Inspectors e.g., WorkSafe, ESV and DJPR ERR. These activities may include inspection of the site, a desk-top review, and an assessment of processes/procedures being utilised and supporting documentation. Defects and/or Opportunities for Improvements (OFIs) identified through these activities are then planned, scheduled and implemented in a timely manner to improve compliance with this Plan.

# 4.21 The policy in relation to assistance to be provided to fire control authorities in the investigation of fires near the specified operator's at-risk electrical lines - reg 6, para (o) Electricity Safety (Bushfire Mitigation) Regulations 2023 (Vic):

The HBESS Fire Management policy is currently being finalised by the Specified Operator and will be implemented as soon as possible. HBESS, in conjunction with HRP, maintains a key stakeholder relationship with the local CFA and FRV due to the high risk of fire to the business.

Regular meetings and joint exercises are held between HBESS, HRP, CFA and FRV.

In line with the Board of Inquiry's October 2014 Report into the Hazelwood Mine Fire Recommendations and Affirmations, a number of additional training, resource sharing and communication initiatives have been implemented between HRP and both the CFA and FRV.

The Project Emergency Response Plan [14343-HAS-GEN-90-003] details the relationship between HBESS, HRP, the CFA/FRV and other state emergency service organisations.

Authoriser: Name Provided

Responsible: Electrical Safety Management System

Folder: VESMS - Voluntary Electricity Safety

 Page:
 12 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

The Project Emergency Response Plan [14343-HAS-GEN-90-003] also details the requirements for statutory investigations as well as regulatory investigations by other emergency services authorities, and the support to be provided by HBESS.

In addition, significant fires are also reported to WorkSafe and DJPR ERR. Should a significant fire be caused by an HBESS site electrical asset, a report would also be provided to ESV.

#### 5 Accessibility of Documents

A copy of the approved ESV version of this Plan is made available for inspection during business hours in accordance with the Electricity Safety Act 1998 (Vic).

An electronic copy of this Plan is made available on the Hazelwood BESS website https://engie.com.au/hazelwoodbattery.

Authoriser: Name Provided Page: 13 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 **Version Date:** 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

### 6 References

Number	Description	Revision No.	Version Date
Paradigm OrigID 2589	Mine Fire Service Policy	3.5	30/09/2021
Paradigm OrigID 36546	Fire Readiness Planning Guidelines	3.10	31/12/2021
Paradigm OrigID 36549	Mine Pre-Fire Season Checklist	2.8	28/06/2022
HP CM MD 18/335	Hazelwood Mine - Risk Management Plan – RMP 3.2	3.2	05/03/2018
Paradigm OrigID 56965	Fire Risk Management Plan (FRMP)	1.1	04/08/2018
14343-HAS-GEN-90-001	Project Health and Safety Management Plan	12	23/02/2023
14343-HAS-GEN-90-003	Project Emergency Response Plan	08	09/11/2022
14343-HAS-GEN-90-009	HBESS Incident Notification Guideline	01	23/11/2021
14343-OAM-FLN-90-001	HBESS HV Maintenance Plan	02	18/08/2023
GHSD-GOV-GR-02	ENGIE Group Health & Safety Rule Health & Safety with regard to Contractors and Subcontractors	6	15/03/2023
HBESS-OP-D-0002	Electric Line Clearance Plan	1	15/09/2023
n/a	Occupational Health and Safety Regulations 2017 (Victorian)		
n/a	Board of Inquiry Report into the Hazelwood Mine Fire (October 2014)		

Authoriser: Responsible: Folder: Name Provided Electrical Safety Management System VESMS - Voluntary Electricity Safety 

 Page:
 14 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

### **Appendix A - Hazelwood BESS Locality Map**




Figure 1: HBESS Locality

Authoriser: Responsible: Folder: Name Provided Electrical Safety Management System VESMS - Voluntary Electricity Safety 

 Page:
 15 of 21

 OrigID:
 58284

 DocID:
 58284

Ver/Status: Version Date: Review Date:

### Appendix B - HBESS High risk transmission line assets




Figure 2: HBESS High risk transmission assets shown in red

Table 1 - Register of HBESS "at risk lines" by Line Nomenclature

Line Nomenclature	Line Voltage	Concrete Poles	Wood Poles	Steel Monopole (31+ metre)	Line Length in Metres	Year of original construction
HWPS-HWBS	220kV	0	0	4	714	2022

Table 2 - Register of HBESS "at risk lines" by Structure

Structure from	Structure To	Phases	Span Length (m)	Conductor
HWBS	Pole 1	3	57.60	TWIN "LEMON" 30/7/3.0 ACSR/GZ.
Pole 1	Pole 2	3	198.24	TWIN "LEMON" 30/7/3.0 ACSR/GZ.
Pole 2	Pole 3	3	262.52	TWIN "LEMON" 30/7/3.0 ACSR/GZ.
Pole 3	Pole 4	3	112.78	TWIN "LEMON" 30/7/3.0 ACSR/GZ.
Pole 4	HWPS	3	82.64	TWIN "LEMON" 30/7/3.0 ACSR/GZ.

Authoriser: Name Provided Page: 16 of 21 Ver/Status: 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

### **Appendix C - Maintenance summary**

#### 18. Transmission line Maintenance Checklist

Inspection item			Assessment ( 6 Months)
	GOOD	POOR	OBS.
General Visual inspection of the whole structure			
Vegetation assessment (control if needed)			

Inspection item	Assessment (3 Yearly)		
SUPPORT POSTS AND REINFORCEMENTS	GOOD	POOR	OBS.
Support accesses. Paths and accesses to support posts			
in good condition.			
Verticality of support post. No collapse, inclination or			
warping and no twisting.			
Condition of metal elements. No rust or buckling on			l i
support post and brace.			
Nuts and bolts, and bars. No material missing on			
support post and on brace.			
Punching of nuts and bolts. All nuts and bolts have been			
punched.			
Condition of foundations. No cracks or fissures, and no			
play with support post.			
Foundation covering. Still covered and correctly			
surfaced.			
Other situations of risk. No water pooling at foot of			
support post.			
Electrical hazard warning plate. There are at least two			
and these are legible.			
Support Post Identification Plate. Support post is			
numbered, and this is legible.			2
Anti-climbing devices , in good condition.			
Torque of Nuts and bolts and bars on column and			
brace. Uprights and latticework are correctly fastened,			
listening to the noises detected as a result of the			
vibrations.			
Leveling of brace. Level and no incline.			
Vegetation assessment: Check for any trees or other			
possible hazard due to nearby vegetation			
Access roads. Vegetation-free, track (where applicable)			
in good condition.			
INSULATOR CHAINS	GOOD	POOR	OBS.
Cleaning insulators. There is no contamination on the			
surface.			

Ver/Status: Authoriser: Name Provided Page: 17 of 21 03 / Current Responsible: Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 VESMS - Voluntary Electricity Safety Folder: DocID: 58284 **Review Date:** 28/06/2024

Inspection item			Assessment (3 Yearly)
General condition of insulators. Breakage. No cracks or			
fissures on the glass or ceramics.			
Rods on ceramic insulators. No loss of material			
observed.			
Rods on compound insulators. No conductor paths			
visible.			2
No of insulators. No insulators missing on any of the			
chains.			
CONNECTIONS	GOOD	POOR	OBS.
Connections. No cracks, rust or signs of overheating.			
No of conductor and ground cable connections. Not			
more than one connection per span length and			
conductor.			
Condition of F.O. connection box In good condition.			
CONDUCTORS	GOOD	POOR	OBS.
Condition of conductor and ground cable. No broken			
strands, rust or dirt.			
Foreign objects on cables. Absence of objects.			
Cable tension. There is parallelism between conductors.			
FITTINGS AND OTHER ELEMENTS MOUNTED ON	GOOD	POOR	OBS.
CONDUCTOR	GOOD	FOOR	OBS.
Fittings on conductors. Correctly mounted, no breaks,			
no loss of material.			
Fittings on ground cable. Correctly mounted, no breaks,			
no loss of material.			
Counterweights. Correctly mounted, no breaks, no loss			
of material.			
Anti vibrators. Correctly mounted, no breaks, no loss of			
material.	1		-
Separators. Correctly mounted, no breaks, no loss of material.			
OPGW FIBER CABLES	GOOD	POOR	OBS.
Condition of F.O. connection box in good overall	GOOD	TOOK	OBS.
condition			
Condition of protective pipe on descent. Correctly			
secured and without rust.			
General condition of cable. Correctly installed and			
without breaks			
Beacons. Anchorage in good condition			
Bird flight diverters. No signs of aging material			
Condition of connection box. Correctly installed,	1		
unbroken and without rust			

Authoriser: Name Provided Page: 18 of 21 Ver/Status: 03 / Current Electrical Safety Management System Responsible: OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

Inspection item	Assessment (3 Yearly)		
GROUNDS		POOR	OBS.
Existence and condition of grounds on support posts.  Cable not frayed or broken			
Disconnection of grounds. Impossible to disconnect grounds from support posts			
Measure of support post ground resistance. (*)			

Authoriser: Name Provided Page: 19 of 21 Ver/Status: 03 / Current Electrical Safety Management System Responsible: OrigID: 58284 Version Date: 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024

### **Appendix D - Electricity Generation And Sale Licence**

OFFICIAL	OFFICIAL	BLECTMONT VERWANDLAND DAIL LICENSE - WIEDLANDERSE STEMANT COPT - LTD
ELECTRICITY GENERATION AND SALE LICENCE  Hazolinoid BESS Project to Pty Ltd  (ACN 643 991 703)	ELECTRONY CORRESPOND LOCATION The Journal is selected in 1 of the JED (10) and selected the terms set and in the JLL (10) and selected the terms set and in the JLL (10) and the	CONTENTS
bessed on 10 August 2022		
Part A Definitions and Interpretation  1.	Hational Descripting	in size to lone, the Monisor  (i) a reference to a document or a provision of all document relucides any  (i) Assemble case in these are  (iii) a reference to the provision of the document of all document or the provision of the the provisi
Automotive detection of the control of the period of the period principle (control of the period of the per	Bullimon's exclusions was old utilized. "everbullnost the first of the control of	times, and the Licenses must notify the Commission of any terms by \$1 of the control of the Licenses must notify the Commission of any terms by \$1 of the control of the Licenses must notify the Commission of the Licenses and L

Ver/Status: Authoriser: Name Provided Page: 20 of 21 03 / Current Electrical Safety Management System OrigID: 58284 Version Date: 27/09/2023 Responsible: VESMS - Voluntary Electricity Safety Folder: DocID: 58284 **Review Date:** 28/06/2024 Experience measurable and use Lucrear - reactions are an experience or propose to revoke the part of the comment of the part of the comment of the part of the comment of the part of the

Authoriser: Name Provided Page: 21 of 21 Ver/Status: 03 / Current Electrical Safety Management System 58284 Responsible: OrigID: **Version Date:** 27/09/2023 Folder: VESMS - Voluntary Electricity Safety DocID: 58284 **Review Date:** 28/06/2024